



Inventor: William D. WILBER, et al.
Apn. No.: 09/987,376 Group Art Unit: 2817
UNABLE TRIPLE-MODE MONO-BLOCK
FILTER ASSEMBLY
SM, PLLC Ref. No.: A8241
SM, PLLC Phone No.: 202-293-7060
Sheet 1 of 16




FIG. 1a





FIG. 1b





Inventor: William D. WILBER, et al.
Apn. No.: 09/987,376 Group Art Unit: 2817
ADJUSTABLE TRIPLE-MODE MONO-BLOCK
FILTER ASSEMBLY
SM, PLLC Ref. No.: A8241
SM, PLLC Phone No.: 202-293-7060
Sheet 3 of 16




FIG. 3a





FIG. 3b

Inventor: William D. WILBER, et al.
Sln. No.: 09/987,376 Group Art Unit: 2817
ADJUSTABLE TRIPLE-MODE MONO-BLOCK
FILTER ASSEMBLY
SM, PLLC Ref. No.: A8241
SM, PLLC Phone No.: 202-293-7060
Sheet 4 of 16



Inventor: William D. WILBER, et al.
In. No.: 09/987,376 Group Art Unit: 2817
UNABLE TRIPLE-MODE MONO-BLOCK
FILTER ASSEMBLY
SM, PLLC Ref. No.: A8241
SM, PLLC Phone No.: 202-293-7060
Sheet 5 of 16




FIG. 5



Inventor: William D. WILBER, et al.
Appl. No.: 09/987,376 Group Art Unit: 2817
UNABLE TRIPLE-MODE MONO-BLOCK
FILTER ASSEMBLY
SM, PLLC Ref. No.: A8241
SM, PLLC Phone No.: 202-293-7060
Sheet 6 of 16




FIG. 6

Inventor: William D. WILBER, et al.
Appl. No.: 09/987,376 Group Art Unit: 2817
TUNABLE TRIPLE-MODE MONO-BLOCK
FILTER ASSEMBLY
SM, PLLC Ref. No.: A8241
SM, PLLC Phone No.: 202-293-7060
Sheet 7 of 16




FIG. 7



Inventor: William D. WILBER, et al.
In. No.: 09/987,376 Group Art Unit: 2817
UNABLE TRIPLE-MODE MONO-BLOCK
FILTER ASSEMBLY
SM, PLLC Ref. No.: A8241
SM, PLLC Phone No.: 202-293-7060
Sheet 8 of 16




FIG. 8a




FIG. 8b



Inventor: William D. WILBER, et al.
Apn. No.: 09/987,376 Group Art Unit: 2817
UNABLE TRIPLE-MODE MONO-BLOCK
FILTER ASSEMBLY
SM, PLLC Ref. No.: A8241
SM, PLLC Phone No.: 202-293-7060
Sheet 9 of 16




FIG. 9

Inventor: William D. WILBER, et al.
Apn. No.: 09/987,376 Group Art Unit: 2817
UNABLE TRIPLE-MODE MONO-BLOCK
FILTER ASSEMBLY
SM, PLLC Ref. No.: A8241
SM, PLLC Phone No.: 202-293-7060
Sheet 10 of 16




FIG. 10a




FIG. 10b



Inventor: William D. WILBER, et al.
Apn. No.: 09/987,376 Group Art Unit: 2817
UNABLE TRIPLE-MODE MONO-BLOCK
FILTER ASSEMBLY
SM, PLLC Ref. No.: A8241
SM, PLLC Phone No.: 202-293-7060
Sheet 11 of 16




FIG. 11d




FIG. 11c




FIG. 11b




FIG. 11a



Inventor: William D. WILBER, et al.
Apn. No.: 09/987,376 Group Art Unit: 2817
UNABLE TRIPLE-MODE MONO-BLOCK
FILTER ASSEMBLY
SM, PLLC Ref. No.: A8241
SM, PLLC Phone No.: 202-293-7060
Sheet 12 of 16




FIG. 12a




FIG. 12b



Inventor: William D. WILBER, et al.
Apn. No.: 09/987,376 Group Art Unit: 2817
UNABLE TRIPLE-MODE MONO-BLOCK
FILTER ASSEMBLY
SM, PLLC Ref. No.: A8241
SM, PLLC Phone No.: 202-293-7060
Sheet 13 of 16




FIG. 13




FIG. 14a




FIG. 14b




FIG. 14c




FIG. 15